

40

Scott M. Matheson, Governor Temple A. Reynolds, Executive Director Dr. G. A. (Jim) Shirazi, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

October 31, 1983

Mr. Kent Dahlquist Mining Engineer Union Carbide Corporation Metals Division LaSal, Utah 84530

> RE: LaSal-Snowball Mining and Reclamation Plan Revision ACT/037/043 San Juan County, Utah

Dear Mr. Dahlquist:

The Division reviewed your revisions in the letter dated August 29, 1983. Thank you for the revised maps, new acreages and bond estimate. There are changes from the previous bond estimate that are not explained. Please explain why the changes were made. The total costs for each item should be detailed, i.e., detail how the cost was derived using the unit costs for each reclamation step. For example:

- How deep will the foundations be buried?
- 2. Where will the structures be removed to?
- 3. What type of hazardous materials will be removed, and how?
- 4. In the previous estimates (1978) there were 11 vent shafts, 1 vertical shaft and 2 declines. Please explain why there are only 11 vent shafts in the new estimate.

Thank you for the information you provided. We are looking foward to resolving these questions.

Sincerely,

PAMELA GRUBAUCH-LITTIG

RECLAMATION ENGINEER

PGL/btb

cc: T. Tetting, DOGM